

— IRELAND —

AIRAC

Phone: +353 (0)61 703 750
Fax: +353 (0)61 366 245
AFS: EINNZPZX
Email: aisops@airnav.ie
URL: <http://www.airnav.ie>



Aeronautical Information Service
Ballycasey Cross
Co. Clare
V14 C446
IRELAND

AIP SUP: 013/2026
Effective Date: 11-Jun-2026
Publication Date: 30-Apr-2026
End Date: 10-Jun-2027

Dublin Airport (EIDW) - Holding Procedure Changed

This AIP Supplement Replaces PERM NOTAM B1138/15.

EIDW AD 2.22 Flight Procedures, Section 8 Holding Procedures

Rate of descent in holding patterns amended to: A standard rate of descent of 1000ft per min in holding patterns will be used unless otherwise instructed by ATC. Pilots must advise ATC if unable to comply with the standard rate of descent.

THIS PAGE INTENTIONALLY LEFT BLANK